## **FIELD INSPECTION REPORT**

Date of	Inspection: 02	12.020	District: Kishangens.		
Division	n: Kishamea	1-Em	Length(km): 4.700 km.		
Name o	of the Road: Ka	Jalamani	DB-50 - Raydaans Pipla.		
	e/Programme:	MAINTENANCE	New MR.		
Package	e No .: PM/KI/	KIS/19/0001			
	of the Project:		eted /Under Maintenance		
Work is	a case of:	~	ty/ Up gradation / Maintenance		
S1. No			s to be checked	Remarks	
1.	Pavement			₩S/U	
a)	Road Junction (	Condition	progress	VS/U	
b)	Condition of Surfacing			V S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			∠ S/U	
e)	Whether free fr in case of CC Pa		as visible cracks, exposed aggregates	A Yes/No	
f)	Contraction Joi	nts Provided or n	ot ( CC Pavement)	A Yes/No	
g)	Compaction of fland / shop & raincuts if any			Yes/No	
2.	Cross Drainage			413	
a)	Condition of he	ad walls in Hume	e pipe culverts including its Painting)	S/SRI/U	
b)				S/SRI/U	
c)				venos/SRI/U	
3.	Road Furniture			and M	
a)	Whether sign boards/informatory/cautionary Board/km & 200m Yes/No				
	stones/Pavement road markings are provided and maintained Information  Compliance History				
4.	Compliance His	tory	Boardiesfi		
a)	Status of ATR's	& any others		NOATR	
	1			Pendery	

## Overall Rating:

Satisfactory(S)	· S'
Satisfactory but requires Improvement (SRI)	_
Unsatisfactory(U)	-

02.12.020 ZE

(Signature)

NAME: