FIELD INSPECTION REPORT

Date o	f Inspection: 02	-12-020	Dis	strict: Kishansans	
	n: Kishams	_	Le	ngth(km): 5.60 km.	
Name	of the Road: BK	athat-than	عذ	beri Amerkali Road.	
Schem	e/Programme:	MAINTENANCE			
Packag	ge No .: RM/KI	/KIS/19/0005	_	Road Id No.:	
_		The second secon	going/Completed /Under Maintenance		
Work i	s a case of:	New Connectivi	ty/	Up gradation / Maintenance	
S1. No		<u>Parameters</u>	s to	be checked	Remarks
1.	Pavement	nt			√S/U
a)	Road Junction Condition				VS/U
b)	Condition of Surfacing				VS/U
c)	Riding Quality				VS/U
d)	Road Camber				₩S/U
e)	Whether free from defects such as visible cracks, exposed aggregates NA Yes/				
	in case of CC P				17
f)	Contraction Joints Provided or not (CC Pavement)				
g)	Compaction of fland / shop & raincuts if any				
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting				s/sri/u
b)	Condition of Abutment & Wing walls, slab in RCC culverts				S/SRI/U
c)	Condition of railings/Slab/approach for Bridges				S/SRI/L
3.	Road Furniture				
a)	The second secon			cautionary Board/km & 200m	Ves/No
			s are	e provided and maintained	
4.	Compliance History				
a)	Status of ATR's & any others			NO ATR	

Overall Rating:

Satisfactory(S)	ری'	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory(U)		

02.12.020

IE

(Signature)

AE.

NAME: