FIELD INSPECTION REPORT

Date of 1 Division)3/12/2020 District: Vatna		
	rar	tha Length (km): 1.50. umaridaulattur Road to Mohammadt	ur Gamaahis	
	Programme:	MAINTENANCE	We from the state of the state	
~		2019-29/10ma/06 Road Id No.:		
Status of	f the Project:	Ongoing/Completed/Under Maintenance		
Work is	a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to be checked	Remarks	
11.	Pavement	Pavement		
a)	Road Junction	condition	S/U	
b)	Condition of S	Condition of Surfacing		
c)		Riding Quality		
d)	Road Camber	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No ///	
f) -	Contraction Joints provided or not (CC Pavement)		Yes/No N/A)	
g)	Compaction of flank/slope & raincuts if any		Yes/No WA	
2.	Cross Draina	ge		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U N/A	
b)	Condition of A	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of ra	Condition of railings/slab/approach for Bridges		
3.	Road Furnitu	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No	
4.	Compliance History			
a)	Status of ATR'		No.	
Overall R	Rating :	rom Gangafur chowk towards north so		
•		Satisfactory (S)	S.	
		Satisfactory but requires Improvement (SRI)		
		Unsatisfactory (U)		

NAME: Jai Brakach Scingh,
DESIGNATION: J.E.

Scanned with CamScanner