

FIELD INSPECTION REPORT

Date of Inspection: 02.12.2020		District: Kishanganj	
Division: Kishanganj-1		Length(km): 5.950 km.	
Name of the Road: Reamening post 5th km of TOS-Ithantibari-amex Kala.			
Scheme/Programme:	MAINTENANCE	NEW MR	
Package No.: RM/KI/KIS/19/0002	Road Id No.:		
Status of the Project:	Ongoing/Completed /Under Maintenance		
Work is a case of:	New Connectivity/ Up gradation / Maintenance		
S1. No	<u>Parameters to be checked</u>	Remarks	
1.	Pavement		
a)	Road Junction Condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No	
f)	Contraction Joints Provided or not (CC Pavement)	N/A Yes/No	
g)	Compaction of fland / shop & raincuts if any	✓ Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓ S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges	✓ S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No ATR	

Overall Rating :

Satisfactory(S)	'S'
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory(U)	—


 02.12.2020
 IE


 2/12/20
 (Signature)
 AE

NAME: