

FIELD INSPECTION REPORT

DATE OF INSPECTION:	04/12/2020	DISTRICT:	PURNEA
DIVISION:	DHAMDHAA	LENGTH:	2.820 km
NAME OF THE ROAD:	Bisoli to Basgaha		
SCHEME/PROGRAMME:	MAINTENANCE		
PACKAGE No:	ROAD ID No.: 220001857		
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE		
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE		
SL.NO	PARAMETERS TO BE CHECKED	REMARKS	
1	PAVEMENT		
A	ROAD JUNCTION CONDITION	S	
B	CONDITION FO SURFACING	S	
C	RIDING QUALITY	S	
D	ROAD CAMBER	S	
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	yes	
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	N.A	
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	S	
2	CROSS DRAINAGE		
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	N.A	
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N.A	
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N.A	
3	ROAD FURNITURE		
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD NARKING ARE PROVIDED AND MAINTAINED	S	
4	COMPLIANCE HISTORY		
A	STATUS OF ATR"s & ANY OTHERS	No Any ATR	
OVERALL RATING			
SATISFACTORY(S)		S	
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)		-	
UNSATISFACTORY(U)		-	

NAME: Kamal Narayan Sharma.
DESIGNATION: Junior Engineer

SIGNATURE

04/12/2020