FIELD INSPECTION REPORT

Date of Inspection: 2.12.2020	District: Kaimar		
Division: Mohawa	Length (km): 11.78		
Name of the Road: Arora to Ti	gna Road.		
Scheme/Programme: MAINTENANCE	MAINTENANCE		1-
Package No.: MR-N/19-20 Mohaly 923 Road Id No.:		100	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity	//Up gradation/ Maintenance		V-5-3-2-5

Parameters to be checked	Remarks
Pavement	454
Road Junction condition	S/U
Condition of Surfacing	S/U
Riding Quality	S/U
Road Camber	S/U
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
Contraction Joints provided or not (CC Pavement)	Yes/No
Compaction of flank/slope & raincuts if any	Yes/No
Cross Drainage	
Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture	
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
Compliance History	
Status of ATR's & any others	
	Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Contraction Joints provided or not (CC Pavement) Compaction of flank/slope & raincuts if any Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Road Furniture Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained Compliance History

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Note - Pot Patch Sterrhed.

(Signature)

NAME: Withou and That