## FIELD INSPECTION REPORT

Date of Inspection: 2.12.2020	District: Yarmur	
Division: Mohawa	Length (km): 0.500	
Name of the Road: TOY to Lurp	urwa	
Scheme/Programme: MAINTENANCE		
Package No.: MR-H/19.20 Mohawa	24 Road Id No.:	
Status of the Project: VOngoing/Complete	ed/Under Maintenance	
Work is a case of: New Connectivity	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	s/U
c)	Riding Quality	s/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4,	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

Note-work not started.

(Signature)

NAME: Nitya rand singh