

FIELD INSPECTION REPORT

Date of Inspection :	03/12/2020	District:	Aurangabad
Division :	AURANGABAD	Length (km):	2.20 K.m
Name of the Road:	Aurangabad Nabinegar road se Sori		
Scheme/Programme:	MAINTENANCE	New Maintenance Policy	
Package No.:	HR-N-19-20 AURAD-33	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	in progress	1
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

NAME: - Dina Nath Rai


 03/12/2020
 (Signature)
 D.E. (R.N.D.)
 Nabinegar