

# FIELD INSPECTION REPORT

Date of Inspection: 03.12.2020

Division: SONPUR

Distrcit: SARAN

Name of the Road: Baksanda - Gangui

Length (km): 3.350

Scheme/Programme: MAINTENANCE

Package No :

Status of The Project: ONGOING

Road ID No :

Work is a case of : Maintenance

| Sl.No | Parameters to be checked                                                                                             | Remarks       |
|-------|----------------------------------------------------------------------------------------------------------------------|---------------|
| 1     | <b>Pavement</b>                                                                                                      |               |
| a)    | Road Junction Condition                                                                                              | S             |
| b)    | Condition of Surfacing                                                                                               | S             |
| c)    | Riding Quality                                                                                                       | S             |
| d)    | Road Camber                                                                                                          | S             |
| e)    | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | No            |
| f)    | Contraction Joints provided or not (CC Pavement)                                                                     | No            |
| g)    | Compaction of Flank/slope & raincuts if any                                                                          | No            |
| 2     | <b>Cross Drainage</b>                                                                                                |               |
| a)    | Condition of head walls in Hume pipe Culverts including its painting                                                 | SRI           |
| b)    | Condition of Abutment & Wing Walls, Slab in RCC Culverts                                                             | SRI           |
| c)    | Condition of railings/slab/approach for Bridges                                                                      | SRI           |
| 3     | <b>Road Furniture</b>                                                                                                |               |
| a)    | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Partially YES |
| 4     | <b>Compliance History</b>                                                                                            |               |
| a)    | Status of ATR's any others                                                                                           | NO            |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            |     |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U)                          |     |

NAME:- RAJEEV RANJAN KUMAR  
DESIGNATION: JUNIOUR ENGINEER

PARSA

Signature

03/12/20