

FIELD INSPECTION REPORT

Date of Inspection :	3/12/20	District:	Murallapur East
Division :	Murallapur East	Length (km):	3.05 km
Name of the Road:	Saraiga kishu vishan kendra to Basolemd via Pipra High school.		
Scheme/Programme:	MAINTENANCE	Road Id No.:	
Package No.:			
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S SU
b)	Condition of Surfacing	S SU
c)	Riding Quality	S SU
d)	Road Camber	S SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
3/12/20
JC