FIELD INSPECTION REPORT

Date of	Inspection :	3/12/20	District: Vai abali		
Division: Half			Length (km): 1.50 km		
Name o	f the Road:	chakahalideux	to chokehelsden Sertin Po	ker Tek	
	/Programme:	MAINTENANG	Cl.		
t mercage			Road Id No.:		
Status of the Project:			Ongoing Completed Under Maintenance New Connectivity/Up gradation/ Maintenance		
Work is a case of:		Annahin amanan a fa a ara		Remarks	
SL No.	(A MORE)	Parameter	s to be checked	Kemarks	
1.	Pavement	F- 1			
a)	Road Junction condition			11 5	
b)	Condition of Surfacing			11 5	
c)	Riding Quality			11 5	
d)	Road Camber			11 5	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes No.	
f)	Contraction J	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any			Yes No.	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			SSRIT	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S SRL1	
c)	Condition of railings'slab/approach for Bridges			SSRIT	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 2000 stones/Pavement road markings are provided and maintained			Jako y	
4.	Compliance History				
a)	Status of ATR's & any others				
Nerall F	Cating :				
, com comp		Satisfactory (S		_S	
			Satisfactory but requires Improvement (SRI)		
		Unsatisfactory	(U)		

(Signature)

NAME:

DESIGNATION:

Alata