FIELD INSPECTION REPORT

Date of	Inspection:	4/11/10	District: Vacation			
Division: Hare			I amount of a			
Name of	the Road:	hosphow to	Length (km): 1.40 Km			
Scheme	og: amme:	MAINTENANO				
Package			Road Id No.:			
Status o	f the Project:	Qagoing/Comp	leted/Under Maintenance			
Work is	a case of:		ity/Up gradation/ Maintenance			
Sl. No.	an andia	Remarks				
1,	Pavement					
a)	Road Junction condition S/					
b)	Condition of S	S/U				
c)	Riding Quality	S/U				
d)	Road Camber	S/U				
			5/0			
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No					
f)	Contraction Joints provided or not (CC Pavement) Ye					
g)	Compaction of flank/slope & raincuts if any Yes/N					
2	Gross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/					
b)	Condition of Abutment & Wing walls, Slab in RCC culverts					
c)	Condition of r	S/SRI/U				
5.	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No					
	Gosphiance I	stately 7		POR LINE		
n)	Status of ATR's & any others					

Overall Rating

Saturfactory (S)	5		
Selfefectory but r	equires	Improvement (SRI)	
Unsatisfactory (U			

(Signature)

HERECKATIONS