

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020	District: Nalanda
Division : HARNAUT	Length (km): 1.80 km
Name of the Road: NH31 to LOHARI	
Scheme Programme: MAINTENANCE	
Package No.	Road Id No.:
Status of the Project: ☒ Ongoing/Completed/Under Maintenance	
Work is a case of: ☒ New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road function condition	☒ S/U
b)	Condition of Surfacing	☒ S/U
c)	Riding Quality	☒ S/U
d)	Road Camber	☒ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ☒
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign ☒ boards/informatory/cautionary Board/km & 200m stones/Pavement road markings ☒ are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	In Progress

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Ajay Kumar Verma
03-12-2020
(Signature)

NAME: AJAY KUMAR VERMA
DESIGNATION: JUNIOR Engineer.