

FIELD INSPECTION REPORT

Date of Inspection :	03-12-2020	District:	Nalanda
Division :	Harnout	Length (km):	1.75 km
Name of the Road:	Bihar Sanf Ekan Kev Path to Ahiyapur		
Scheme Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
	Read Junction condition	✓ S/U
	Condition of Surfacing	✓ S/U
	Riding Quality	✓ S/U
	Road Camber	✓ S/U
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
	Contraction Joints provided or not (CC Pavement)	Yes/No
	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	✓ 3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Ajay Kumar Verma
03-11-2020
(Signature)

NAME: *AJAY KUMAR VERMA*

DESIGNATION: