

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020	District: Nalanda
Division : HARNAUT	Length (km): 4.35KM
Name of the Road: Link Road fr Nroscrai Nalanda Path Bara Kurd	
Scheme Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
	Road Junction condition	✓ S/U
	Condition of Surfacing	✓ S/U
	Riding Quality	✓ S/U
	Road Camber	✓ S/U
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
	Contraction Joints provided or not (CC Pavement)	Yes/No
	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign ✓ boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained ✓	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	In Progress

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

03-12-2020
(Signature)

NAME: AJAY KUMAR VERMA
DESIGNATION: JUNIOR Engineer.