FIELD INSPECTION REPORT

Date of	Inspection: 7	3/12/2020	Districts Gaya	
Division: Sherghati			Length (lon): 5.3 km	
Name a	f the Road; (IT Road to	BUMER	
Scheme	Programme:	MAINTENANCE		
Package			Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
Work is a case of:				Remarks
Sl. No.		Parameters t	n be checked	
1.	Pavement S/U			9/11
3)	Road Junction condition S			
b).	Condition of Surfacing S			S/U
_	S			S/U
6)	Kinning County			S/U
d)	Read Camber			Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
	Contraction I	sints emvided of not	Yes/No	
1)	Contraction Joints provided or not (CC Pavement) NA Yes			Yes/No
g)	Compaction of manie stope & famedo it any			11111
2.	Cross Drainage - In Progress.			S/SRI/U
2)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
	Road Furniture			
3.				V. 20
a)	Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			NO.

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

(Signature)

NAME: Suzesh Prasad Singh. ----- AE, Basachatti