

# FIELD INSPECTION REPORT

|                        |                                            |              |         |
|------------------------|--------------------------------------------|--------------|---------|
| Date of Inspection :   | 3-12-2020                                  | District:    | Gaya    |
| Division :             | Gaya                                       | Length (km): | 3.82 km |
| Name of the Road:      | Bakraur Sukhdevchak To Nima                |              |         |
| Scheme/Programme:      | MAINTENANCE                                | New Policy   |         |
| Package No.:           |                                            | Road Id No.: |         |
| Status of the Project: | Ongoing/Completed/Under Maintenance        |              |         |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |         |

| Sl. No. | Parameters to be checked                                                                                             | Remarks     |
|---------|----------------------------------------------------------------------------------------------------------------------|-------------|
| 1.      | Pavement                                                                                                             |             |
| a)      | Road Junction condition                                                                                              | ✓ S/U       |
| b)      | Condition of Surfacing                                                                                               | ✓ S/U       |
| c)      | Riding Quality                                                                                                       | ✓ S/U       |
| d)      | Road Camber                                                                                                          | ✓ S/U       |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓ Yes/No NA |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ Yes/No NA |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No    |
| 2.      | Gross Drainage                                                                                                       |             |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U NA  |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U NA  |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U NA  |
| 3.      | Road Furniture                                                                                                       |             |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No    |
| 4.      | Compliance History                                                                                                   |             |
| a)      | Status of ATR's & any others                                                                                         | NA          |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

03/12/2020  
(Signature)

NAME: Shreshyams Pathak Pankaj

DESIGNATION: P.E.