

FIELD INSPECTION REPORT

Date of Inspection :	3/12/20	District:	Gayu.
Division :	Imangamj.	Length (km):	1.5 k.m.
Name of the Road:	Imangamj-Daman'a Rd (SH 69) to pankara.		
Scheme/Programme:	MAINTENANCE ✓		
Package No.:	MR-N 19-20/mmm/04	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance Not Started.		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U U	
a)	Road Junction condition	S/U U	
b)	Condition of Surfacing	S/U U	
c)	Riding Quality	S/U U	
d)	Road Camber	S/U U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No.	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes.	
g)	Compaction of flank/slope & raincuts if any	Yes/No No.	
2.	Cross Drainage	S/SRI/U U	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U SRI.	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U SRI.	
3.	Road Furniture	Yes/No No.	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No No.	
4.	Compliance History	No	
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

U

(Signature) A.E.

NAME: G.S. yeehu (A.E) Daman'a.