FIELD INSPECTION REPORT

Date of Inspection:	3/12/20	District: PATNA
Division: 3 D	ANAPUR	Length (km): 3.350
Name of the Road:	Bilta Lou F	2d to KaliganJ.
Scheme/Programme:	MAINTENANCE	
Package No.: MR-N/1	9-20-Dampus/02	Road Id No.:
Status of the Project: \	Ongoing/Completed	/Under Maintenance
Work is a case of:	New Connectivity/L	Jp gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks	
11.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture	And the state of t	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	, Aj	

work not Started

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

J.E Billa Amil Kumar

(Signature)

NAME:

DESIGNATION: