## FIELD INSPECTION REPORT

TATA OF IT	tion t	place District: Patra,	
		2 12 70 70	
Division :	the Road:	Patra Masaurhi to Elahibagh.	
	rogramme:	MAINTENANCE New Maintenance P	olicy
Package		Road Id No.:	U
	the Project:	Ongoing/Completed/Under Maintenance New M	aintenance
Work is	a case of:	New Connectivity/Up gradation/ Maintenance	200
SI. No.	-N/A-	Parameters to be checked	Remarks
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
2	Cross Drain	age NA	
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
A	Compliance History - NA		
	Status of AT	R's & any others	<b>建设建设</b>
a)			
a) Overall	Rating	Satisfactor (5)	- to s
	Rating	Satisfactory (S)  Satisfactory but requires Improvement (SRI)	1030

NAME: SUPRIFA PANIL

DESIGNATION: ASistant engineer ,
RWD(10) sub-Division
sampatchak.

= supery 9 02/12/20.

(Signature)