

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020	District: Patna
Division : Patna	Length (km): 2.350
Name of the Road: P19657 Road to Harashi	
Scheme/Programme: MAINTENANCE	
Package No.: MR-11/2019-20/PATNA/13	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	(Work not started)
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU NA
b)	Condition of Surfacing	SU NA
c)	Riding Quality	SU NA
d)	Road Camber	SU NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No/NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No/NA
g)	Compaction of flank/slope & raincuts if any	Yes/No/NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No/NA
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating : Work not started

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	NA
Unsatisfactory (U)	

NAME: Himanshu Raj
DESIGNATION: Assistant Engineer

Himanshu Raj
03.12.2020
(Signature)