FIELD INSPECTION REPORT

Date of Inspection: 2-12-20 District: 1000			District: Kenny	and the second second
Division: Bhapus			Length (km): 5.99	
Name of	the Road: Ke	Sari eland 24	rgeweb Roxal Bayri to K	avaju
Scheme/Programme: MAINTENANCE				
Package No.: BR-N /2019-20/02		12019-20102	Road Id No.: NEA2200099	9
Status of the Project: Ongoing/Completed/Under Maintenance		d/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance				
Sl. No.	The same of	Parameters to	be checked	Remarks
1.	Pavement	7.2		
a)	Road Junction			~5/U
b)	Condition of Surfacing			18/U
c)	Riding Quality			VS/U -
d)	Road Camber			√s/U
c)	Whether fre aggregates in	e from defects su case of CC Pavemer	ch as visible cracks, exposed	Yes/No

AIK 711A

	_ So. Barre III Cast of CC Lavellicity			
ŋ	Contraction Joints provided or not (CC Pavement)	Yes/No	1	
g)	Compaction of flank/slope & raincuts if any	Yes/No		
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRL/U	1	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U -	1	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U _	ł	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Ýes/No	100	
4.1	Compliance History	16.11 6 77267	* 1	
a)	Status of ATR's & any others	No		

Overall Rating

Satisfactory (S)	U.S.
Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	

(Signature)

NAME: - Poission Ofiteri single
DESIGNATION: Allix. Enfineer

Scanned with CamScanner