

FIELD INSPECTION REPORT

Date of Inspection : 2/12/2020	District: Samastipur
Division : Dalsingh Sarai	Length (km): 2.55
Name of the Road: NH 103 to Pursatampur	
Scheme/Programme:	MAINTENANCE policy
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>
Work is a case of:	New Connectivity/Up gradation/ Maintenance <input checked="" type="checkbox"/>

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No S
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Mananjoy Prasad

DESIGNATION: J.E.

(Signature) *[Signature]*
2/12/2020
J.E.