## FIELD INSPECTION REPORT

Date of	nspection : e 4	- 12 - 2020	District: West Champa	ran
Date of Inspection: e 4- 12 - 2020  Division: Bagaha - 1			Length (km): 2.70 Km	
Name of	the Road:		0 0	
Scheme/	Programme:	MAINTENANCE	igan se Barbira	
Package			Road Id No.:	
Status o	the Project:	Ongoing/Completed	Under Maintenance	
Work is	a case of:	New Connectivity/U	p gradation/ Maintenance	
Sl. No.	Sl. No. Parameters to be ch		be checked	Remarks
1.	Pavement			
a)	Road Junction condition			VS/U
b)	Condition of Surfacing			∨s/u
c)	Riding Quality			<b>√</b> S/U
d)	Road Camber			Vs/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			VYes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			√S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			VS/SRI/U
c)	Condition of railings/slab/approach for Bridges			VS/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Lyes/No
4.	Compliance History			
a)	Status of ATR's & any others			

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: SANTOSH KUMPR CHAUBEY

DESIGNATION: J.E.