

# FIELD INSPECTION REPORT

|                        |                                              |              |                |
|------------------------|----------------------------------------------|--------------|----------------|
| Date of Inspection :   | 04.12.2020                                   | District:    | West Champaran |
| Division :             | Nazkatiagari                                 | Length (km): | 2.58           |
| Name of the Road:      | Beta Lauriya to Mushahari                    |              |                |
| Scheme/Programme:      | MAINTENANCE                                  |              |                |
| Package No.:           |                                              | Road Id No.: |                |
| Status of the Project: | Ongoing/Completed/Under Maintenance          |              |                |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance ✓ |              |                |

| Sl. No. | Parameters to be checked                                                                                             | Remarks |
|---------|----------------------------------------------------------------------------------------------------------------------|---------|
| 1.      | <b>Pavement</b>                                                                                                      |         |
| a)      | Road Junction condition                                                                                              | Ongoing |
| b)      | Condition of Surfacing                                                                                               | "       |
| c)      | Riding Quality                                                                                                       | "       |
| d)      | Road Camber                                                                                                          | "       |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | NA      |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | NA      |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | NO      |
| 2.      | <b>Cross Drainage</b>                                                                                                |         |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | NA      |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | Ongoing |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | NA      |
| 3.      | <b>Road Furniture</b>                                                                                                |         |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Ongoing |
| 4.      | <b>Compliance History</b>                                                                                            |         |
| a)      | Status of ATR's & any others                                                                                         | -       |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) | - |
| Unsatisfactory (U)                          | - |

*[Signature]*  
04/12/20  
(Signature)

NAME: JAY PRAKASH RAM

DESIGNATION: JP