

FIELD INSPECTION REPORT

Date of Inspection: 04-12-2020	District: Arwal
Division: Arwal	Length (km): 1.40 km
Name of the Road: Mahua bagha to Main road Baidrahal via Malhipti	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 14311032402
Status of the Project: ☒ Ongoing/Completed Under Maintenance <i>ongoing</i>	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/S
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

work just started

Overall Rating	<i>work just started</i>	
	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

[Signature]
04/12/2020
(Signature)

NAME: Indrajit Ram
J.E.