

FIELD INSPECTION REPORT

Date of Inspection :	4/12/20	District:	Syaul
Division :	works div. Virpur	Length (km):	2.714
Name of the Road:	Bhagwamber to Bolawa		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR/1/20-21 Virpur/OJ	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U✓
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	S/U✓
d)	Road Camber	S/U✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No✓
g)	Compaction of flank/slope & raincuts if any	Yes/No✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	1
Satisfactory but requires Improvement (SRI)	1
Unsatisfactory (U)	0

(Signature) *Xh*
4/12/2020

NAME: *Tifendra Kumar Singh*

DESIGNATION: *A.E., R.W.D.(C) Sub-div -
Basantpur, div - Virpur*