FIELD INSPECTION REPORT

Date of Inspection: 5/12/20			District: Jamyi	
Division: Jamui			Length (km): 1.117 Km	
			oud from Sighauri Road	ro choran
	Programme:	MAINTENANCE		
0.71	C AND UNION CONTROL OF	19-20/Jamui - 21	The State of the S	12465
	of the Project:		ted/Under Maintenance	1242-1
			/Up gradation/ Maintenance	A THE STATE OF THE
SI-No.		e le la como de la com	to be checked.	Remarks
	Pavement	Later at the		
a)	Road Junction	Road Junction condition		
b)	Condition of Surfacing			√\$7U
c)	Riding Quality			√\$ /U
d)	Road Camber			√87 U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No N-A
f)	Contraction Joints provided or not (CC Pavement)			YesNo
g)	Compaction of flank/slope & raincuts if any			Yes/No
	Crois Denin	ige		and Name of
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI			8/SRI/U
b) '	Condition of Abutment & Wing walls, Slab in RCC culverts			- S/SRI/U -
c)	Condition of railings/slab/approach for Bridges			-S/SRI/U
	Rockinbure			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
學情報		illing a The	2012年中的 共 和公司会	457.3
a)	Status of ATR's & any others			NA

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

05-12 20 OF 5/12/10

Executive Eligineer RWD Works Wilsion, Jamui

NAME:

DESIGNATION: