

FIELD INSPECTION REPORT

Date of Inspection : 4/12/20	District: Nalanda
Division : Rajgir	Length (km): 0.900 km
Name of the Road: Rajgir chabilapur to gorouy	
Scheme/Programme: MAINTENANCE (3054 mR)	
Package No.: RM/NA/RAJ/19/0003	Road Id No.: 1291032858
Status of the Project: Ongoing/Completed/Under Maintenance	ongoing
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Rampreesh Kumar

JE

NAME: Rajgir

4/12/23
(Signature)