

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: Madhapura	
Division : Udakisingang		Length (km): 4.00 km	
Name of the Road: Bhatgama zero mile to Manoharpur			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U	N.A.
a)	Road Junction condition	S/U	N.A.
b)	Condition of Surfacing	S/U	N.A.
c)	Riding Quality	S/U	N.A.
d)	Road Camber	S/U	N.A.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N.A.
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No	
2.	Cross Drainage	S/SRI/U	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	} work in progress
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Remarks:- work in progress.

(Signature)

NAME: