

FIELD INSPECTION REPORT

(Block - Jagdishpur)

Date of Inspection : 04-12-2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 0.500 Km.	
Name of the Road : PWD Road Makaspur Road (Kann Tola) TO Makaspur Harjain Tola.			
Scheme / Programme : MAINTENANCE			
Package No. : Group No. 12		Road Id No. : 27321033243.	
Status of the Project : ☒ Ongoing / ☐ Completed / ☐ Under Maintenance			
Work is a case of : ☒ New Connectivity / ☐ Up gradation / ☐ Maintenance			
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	NA
b)	Condition of Surfacing	S/U	NA
c)	Riding Quality	S/U	NA
d)	Road Camber	S/U	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	NA
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S-SRI/U	} NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S-SRI/U	
c)	Condition of railings/slab/approach for Bridges	S-SRI/U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes/No	NO
4.	Compliance History		
a)	Status of ATR's & any others	NO	
Overall Rating : <u>work has not been started yet.</u>			
	Satisfactory (S)	-	
	Satisfactory but requires Improvement (SRI)	SRI	
	Unsatisfactory (U)	-	

NAME :

Raddo Raman Singh.

DESIGNATION :

Assistant Engineer.

Signature
04/12/20.
J.E.

(Signature)

Signature
04/12/20
AE