

FIELD INSPECTION REPORT

(Block - Jagdishpur)

Date: 04-12-2020		District: Bhagalpur	
Bhagalpur		Length (Km): 2.55 Km.	
Name of the Road: Bhagalpur Baunshi Road Ke Jagdishpur Market to Bada Hassanpur Road.			
Scheme / Programme: MAINTENANCE			
Package No.: Group No. 13.		Road Id No.: 2732-1033246.	
Status of the Project: ☒ Ongoing / ☐ Completed / ☐ Under Maintenance			
Work is a case of: ☒ New Connectivity / ☐ Up gradation / ☐ Maintenance			
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	NA
b)	Condition of Surfacing	S/U	NA
c)	Riding Quality	S/U	NA
d)	Road Camber	S/U	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	} NA
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	
g)	Compaction of flank/slope & raincuts if any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	} NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	NO
4.	Compliance History		
a)	Status of ATR's & any others	NO	
Overall Rating: Work has not been started yet.			
	Satisfactory (S)	—	
	Satisfactory but requires Improvement (SRI)	SRI	
	Unsatisfactory (U)	—	

NAME: Radha Ramon Singh
DESIGNATION: Assistant Engineer

Archa
04/12/20
J.E.

(Signature)

Sky
04/12/20
AE