FIELD INSPECTION REPORT

The action in				
Date of I	nspection : 0	3/12/2020	District: Rohfoy	
Division: SeAx Length (km): 3.110 K				M
	the Road: A	ruchmi do	has to Raydown Do	from
	Programme:	MAINTENANCE	MR rlest	
Package			Road Id No.:	
	the Project:		d/Under Maintenance	
DESCRIPTION OF THE PERSON NAMED IN	a case of:		Up gradation/ Maintenance	
Sl. No.	Car Salah a	Parameters to	be checked	Remarks
1,	Pavement	mental T		
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
n	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drain	nge	The state of the s	
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			

Overall Rating Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U) This road is transfer to RCD Ani Pood construction Department 03/12/2020

NAME: AVENIASH RUMAR
DESIGNATION: Agustomt Engancer (A.E)

Scanned with CamScanner