

FIELD INSPECTION REPORT

Date of Inspection: - 3-12-20	District: Noida
Division: H-1/57	Length (km):
Name of the Road: Gharabigha to Ankit	
Scheme/Programme: MAINTENANCE	
Package No.: -	Road Id No.: -
Status of the Project: Ongoing/Completed/Under Maintenance	Ongoing
Work is a case of: New Connectivity/Up gradation/ Maintenance	Upgradation

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Rolling Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No -
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U S
c)	Condition of railings/slab/approach for Bridges	S/SR/U S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/kerb & stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Score of ATR's & any other	N/A

Overall Rating

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SR)	
Unsatisfactory (U)	

NAME:

Pradeep Kumar Arya
J.E.

Arm
3/12/20