

FIELD INSPECTION REPORT

Date of Inspection: 02/12/2020 District: - Nalanda
 Division: - H.H&A Length (km): 1.500 km
 Name of the Road: Sultanpur Nalanda Bypass Road to Nalanda
 Scheme Programme: MAINTENANCE
 Package No.: Road Id No.:
 Status of the Project: Bidding/Completed Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Construction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & minecuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

N/A
N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires improvement (SRI)	-
Unsatisfactory (U)	-

This road is in work New maintain propose

Tarun Kumar

Tarun Kumar
02/12/2020
(Signature) J2

NAME: