

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Nalanda
Division :	HILSA	Length (km):	1.32 km
Name of the Road:	Ekangarsarai - Parwalpur Path se A. H. Chandra chauraha to Radis a tal		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
Pavement		
a)	Road Junction condition	work in progress S/U
b)	Condition of Surfacing	under new main Policy S/U
c)	Riding Quality	2018 S/U
d)	Road Camber	Pot patches work done & work in progress
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compection of flank/slope & raincuts if any	Yes/No
Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No
Compliance History		
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

ANDANE KUMAR
NAME:

(Signature) 02/12