

# FIELD INSPECTION REPORT

|                                                               |                         |
|---------------------------------------------------------------|-------------------------|
| Date of Inspection : 5/12/20                                  | District: Nalanda       |
| Division : Rajgir                                             | Length (km): 0.910 km.  |
| Name of the Road: Rajgir Chabilapur to Thera                  |                         |
| Scheme/Programme: MAINTENANCE (3054-MR)                       |                         |
| Package No.: RM/NA/RAJ/20/0003                                | Road Id No.: 1291033629 |
| Status of the Project: Ongoing/Completed/Under Maintenance    | ongoing                 |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |                         |

| Sl. No. | Parameters to be checked                                                                                             | Remarks        |
|---------|----------------------------------------------------------------------------------------------------------------------|----------------|
| 1.      | Pavement                                                                                                             |                |
| a)      | Road Junction condition                                                                                              | S/U            |
| b)      | Condition of Surfacing                                                                                               | S/U            |
| c)      | Riding Quality                                                                                                       | S/U            |
| d)      | Road Camber                                                                                                          | S/U            |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No (N/A)   |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No (N/A)   |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No         |
| 2.      | Cross Drainage                                                                                                       |                |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U (N/A)✓ |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U (N/A)✓ |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U (N/A)✓ |
| 3.      | Road Furniture                                                                                                       |                |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No       |
| 4.      | Compliance History                                                                                                   |                |
| a)      | Status of ATR's & any others                                                                                         |                |

Overall Rating :


Satisfactory (S)

S

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Rampresh Kumar  
 NAME: Jt  
 Rajgir

  
 4/12/20  
 (Signature)