


# FIELD INSPECTION REPORT

Inspection: 05/12/20 | District: Bhagalpur  
 Division: Bhagalpur | Length (Km): 1.55  
 Name of the Road: Bhagalpur hasan chak to harnathpur via Chandramagon  
 Scheme / Programme: MAINTENANCE C.S. process.  
 Package No.: group - 18 | Road Id No.: 27321033691  
 Status of the Project: Ongoing / Completed / Under Maintenance C.S. process  
 Work is a case of: New Connectivity / Up gradation / Maintenance

SL. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No
f)	Contraction Joints provided or not (CC Pavement)	Yes / No
g)	Cmpaction of flank/slope & raincuts if any	Yes / No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U
c)	Condition of railings/slab/approach for Bridges	S / SRI / U
3.	<b>Road Furniture</b>	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	
Overall Rating: A.A is given & This road is in under tender process.		
	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	N/A
	Unsatisfactory (U)	

NAME: Radha Ramon Singh  
 DESIGNATION: A.E

(Signature)   
 05/12/20  
 RE