

FIELD INSPECTION REPORT

Inspection on 5/12/20 | District : Bhagalpur
 Division : Bhagalpur | Length (Km) : 1.07
 Name of the Road : Kolanarayanpur Southern to Brahman to Yadav to
 Scheme / Programme : MAINTENANCE 27321033864
 Package No. : group - 16 | Road Id No. : 27321033864
 Status of the Project : Ongoing / Completed / Under Maintenance C.S. process
 Work is a case of : New Connectivity / Up gradation / Maintenance

SL. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No C.S
f)	Contraction Joints provided or not (CC Pavement)	Yes / No process
g)	Compaction of flank/slope & raincuts if any	Yes / No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U
c)	Condition of railings/slab/approach for Bridges	S / SRI / U
3.	Road Furniture	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No
4.	Compliance History	
a)	Status of ATR's & any others	
Overall Rating: A.A In given 9 this road is in the under the process.		
	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

NAME : Radha Raman Singh
 DESIGNATION : A.E

(Signature)

5/12/20
 A.E