

FIELD INSPECTION REPORT

Inspection : 05/12/20 | District : Bhagalpur
 Division : Bhagalpur | Length (Km) : 2.300
 Name of the Road : Railway line (crossing) / Makdampur
 Scheme / Programme : MAINTENANCE
 Package No. : group - 20 | Road Id No. : 27321033865
 Status of the Project : Ongoing / Completed / Under Maintenance C.S. broken.
 Work is a case of : New Connectivity / Up gradation / Maintenance

SL. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No
f)	Contraction Joints provided or not (CC Pavement)	Yes / No
g)	Compaction of flank/slope & raincuts if any	Yes / No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U
c)	Condition of railings/slab/approach for Bridges	S / SRI / U
3.	Road Furniture	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No
4.	Compliance History	
a)	Status of ATR's & any others	
Overall Rating A.A. Given & This Road is in under repair process.		
	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

NAME :

Radha Raman Singh

DESIGNATION :

AE

(Signature)

05/12/20
hr