FIELD INSPECTION REPORT

			LION REPORT		
te of Insp	ection: De	-12-2020			
Division: Related					
me of the	: Mount: War	alan Kataicaan	Length (km): 0.550 pcm/ PWD Road Dubjabilian Kluth	Vale Teta	
heme/l're	gramme:	MAINTENANCE	New Maintenance Policy	2018	
ckage No).;		Road Id No.	2010	
ork is a c	e Project:	Ongoing/Completed	Under Maintenance		
L No.	#36 01:	New Connectivity/L	In gradation/ Maintenance		
_	Parameters to be checked		Remarks		
1, 1	Pavement				
a) I	Road Junction condition S/U				
b)	Condition of Surfacing				
	Riding Quality			S/U	
	Road Camber			S/U	
	Whether for S				
ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & minute is			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
b)	Condition of Abutment & Wing walls Slot in Dog				
c)	Condition of railings/slah/approach for Bridges			S/SRI/U	
3.	Road Furniture			S/SRI/U	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			Yes/No	
4.5	Compliance History			1.4000	
a)	Status of ATR's & any others			-	

Overall Rating :

isfactory (S)	
isfactory but requires Improvement (SRI)	2,
satisfactory (U)	\\\'
satisfactory (U)	

(Signature)

NAME: Arvind Keener

DESIGNATION: J-R

Scanned with CamScanner