FIELD INSPECTION REPORT

Date of In	spection: 05-12-2020 District: Nalanda	
Division :		
Name of	he Rond: Cholology On Alexandra	~ Mushan
	MAINTENANCE Bloom At an Inches	y 2018
Package	10 ad 10 10,.	
Work in	the Project: Ongoing/Completed/Under Maintenance case of: New Connectivity/In gradation/ Maintenance	
	case of: New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
n)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U S/U S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
n	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slah/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.50	Compliance History	
a)	Status of ATR's & any others	
		1

Overall Rating :

Satisfactory (S)	N
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Around Kumar

DESIGNATION: J-&

Scanned with CamScanner