## FIELD INSPECTION REPORT

Date of Inspection: 05-12-2020 District: Pruza ffar pr			m	
Division: Pruz - East - 2 Length (km Name of the Road: Minapur Pranhand Antara Scheme/Programme: MAINTENANCE thu 6763 Package No.:			th (km): 3.58	
Name o	f the Road: M	inapur Pranhand An	starget Rampun 1	teri to c
Dank	Programme:	MAINTENANCE Lu	e Grandhinager ch	lowx Jas
		Koad Id No.:		
Work is a case of:		Ongoing/Completed/Under Maintenance  New Connectivity/Up gradation/ Maintenance		
SI. No.		ARTON CONTROL OF THE PARTY OF T		
				Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)*	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m Yes/No			
4.	Compliance History			E <sub>1</sub> ·
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

> 05.12.202 (Signature)

NAME: Kamte pel Sigs
DESIGNATION: JE minapur