

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District:	BANKA
Division :	BANKA-2	Length (km):	2.473
Name of the Road:	Bhagalpur-Dumka Road To Upama		
Scheme/Programme:	MAINTENANCE, M/R, New (3054)		
Package No.:	RM/BA/BAN/20/0013	Road Id No.:	20703502065
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	on going
b)	Condition of Surfacing	S/U	on going
c)	Riding Quality	S/U	on going
d)	Road Camber	S/U	on going
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No	on going
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	on going
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	on going
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N/A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	on going
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Aji
04.12.2020
(Signature)

NAME: *Ajay Kumar*

DESIGNATION: *AE.*