

# FIELD INSPECTION REPORT

Date of Inspection :	4/1/20	District:	Banka
Division :	Banka-2	Length (km):	2.85
Name of the Road:	BGL Dinnaka Road to Mirzapur		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-20 Banka 2/62	Road Id No.:	20703502067
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U ongoing
b)	Condition of Surfacing	S/U on going
c)	Riding Quality	S/U on going
d)	Road Camber	S/U on going
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U On going
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U on going
c)	Condition of railings/slab/approach for Bridges	S/SRI/U on going
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No on going
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 4/1/20

NAME: Sampat Kr Yadav.

DESIGNATION: AE