

# FIELD INSPECTION REPORT

Date of Inspection :	04/12/20	District:	Banka
Division :	Banka-1	Length (km):	0.760
Name of the Road:	English more shambhuganj road to chorvey		
Scheme/Programme:	MAINTENANCE		
Package No.:	Rm/BA/BAN/20/0002	Road Id No.:	20703502078
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	<b>Pavement</b>		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	ongoing
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	ongoing
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	ongoing
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

*Dharmveer*  
04/12/20  
(Signature)

NAME: DHARMVEER KUMAR

DESIGNATION: J.E.