

# FIELD INSPECTION REPORT

| Date of Inspection : 04-12-2020                   |                                                                                                                      | District: BANKA                            |          |
|---------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|--------------------------------------------|----------|
| Division : BANKA-2                                |                                                                                                                      | Length (km): 2.10                          |          |
| Name of the Road: Punseya - chikour Road To Asota |                                                                                                                      |                                            |          |
| Scheme/Programme:                                 |                                                                                                                      | MAINTENANCE, M/R (3054) New                |          |
| Package No.: RM/BA/BAN/20/0013                    |                                                                                                                      | Road Id No.: 20703502100                   |          |
| Status of the Project:                            |                                                                                                                      | Ongoing/Completed/Under Maintenance        |          |
| Work is a case of:                                |                                                                                                                      | New Connectivity/Up gradation/ Maintenance |          |
| Sl. No.                                           | Parameters to be checked                                                                                             | Remarks                                    |          |
| 1.                                                | <b>Pavement</b>                                                                                                      |                                            |          |
| a)                                                | Road Junction condition                                                                                              | S/U                                        | on going |
| b)                                                | Condition of Surfacing                                                                                               | S/U                                        | on going |
| c)                                                | Riding Quality                                                                                                       | S/U                                        | on going |
| d)                                                | Road Camber                                                                                                          | S/U                                        | on going |
| e)                                                | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No                                     | N/A      |
| f)                                                | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No                                     | N/A      |
| g)                                                | Compaction of flank/slope & raincuts if any                                                                          | Yes/No                                     | on going |
| 2.                                                | <b>Cross Drainage</b>                                                                                                |                                            |          |
| a)                                                | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U                                    | on going |
| b)                                                | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U                                    | on going |
| c)                                                | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U                                    | N/A      |
| 3.                                                | <b>Road Furniture</b>                                                                                                |                                            |          |
| a)                                                | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No                                     | on going |
| 4.                                                | <b>Compliance History</b>                                                                                            |                                            |          |
| a)                                                | Status of ATR's & any others                                                                                         | —                                          |          |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

Aj  
04.12.2020  
(Signature)

NAME: Ajay Kumar  
DESIGNATION: AE