


FIELD INSPECTION REPORT

Date of Inspection :	4/12/20	District:	Banka
Division :	Banka - 2	Length (km):	
Name of the Road:	Rumsia Ghosia Road to Kolhatta		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-20 Banka 2	Road Id No.:	20709502103
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ongoing
b)	Condition of Surfacing	S/U ongoing
c)	Riding Quality	S/U ongoing
d)	Road Camber	S/U ongoing
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No —
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ongoing
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ongoing
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ongoing
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	✓ (S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


4/12/20
(Signature)

NAME: P. K. Kumari
DESIGNATION: J.E