

FIELD INSPECTION REPORT

Date of Inspection :	5/12/2020	District:	Banka
Division :	RWD(W) Division Banka-2	Length (km):	6.400
Name of the Road:	Inaravaran to Pipradih		
Scheme/Programme:	MAINTENANCE		
Package No.:	RM/BA/BAN/20/0012	Road Id No.:	20708602038
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U <i>ongoing</i>
b)	Condition of Surfacing	S/U "
c)	Riding Quality	S/U "
d)	Road Camber	S/U "
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <i>NA</i>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <i>NA</i>
g)	Compaction of flank/slope & raincuts if any	Yes/No <i>Ongoing</i>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <i>ongoing</i>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U "
c)	Condition of railings/slab/approach for Bridges	S/SRI/U "
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No "
4.	Compliance History	
a)	Status of ATR's & any others	<i>NA.</i>

Overall Rating :

☒ Satisfactory (S)	
☐ Satisfactory but requires Improvement (SRI)	
☐ Unsatisfactory (U)	

Note: - Work has been started. E/W & WBM in progress.

am
5/12/2020
(Signature)

NAME: *Bikrama Prasad*

DESIGNATION: *Assistant Engineer*
Katoriya