

FIELD INSPECTION REPORT

Date of Inspection : 5/12/2020	District: Banka
Division : RWT(W) Division, Banka-2	Length (km): 4.600
Name of the Road: Sonawaran to Tahsariya	
Scheme/Programme: MAINTENANCE	
Package No.: RM/BALBAN/20/0012	Road Id No.: 20703602064
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U Ongoing
b)	Condition of Surfacing	S/U " "
c)	Riding Quality	S/U " "
d)	Road Camber	S/U " "
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No Ongoing
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U Ongoing
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U " "
c)	Condition of railings/slab/approach for Bridges	S/SRI/U " "
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No " "
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

☒ Satisfactory (S)	
☐ Satisfactory but requires Improvement (SRI)	
☐ Unsatisfactory (U)	

Note:- Work has been started. E/W & WBM in progress.

[Signature]
(Signature) 5/12/20

NAME: Bikrama Prasad
DESIGNATION: Assistant Engineer